

## HISTORIC AMERICAN ENGINEERING RECORD

### INDEX TO PHOTOGRAPHS

BEACON MARINE BASIN  
211 East Main Street  
Gloucester  
Essex County  
Massachusetts

HAER MA-163

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

John Tagiuri, photographer, 2008

MA-163-1	Elevation of pier building and main house looking south. Building at far right was fish smokehouse. Roof of building at right was used for drying fish.
MA-163-2	3/4 view from street looking southwest towards main structure and pier buildings on right.
MA-163-3	3/4 view of street facade looking northwest.
MA-163-4	3/4 view of southwest corner looking northwest from the street.
MA-163-5	Elevation of main building, pier structure and boat lift looking north from parking lot.
MA-163-6	Stiff leg crane used for boat hoist.
MA-163-7	Detail of stiff leg crane base and control house at left.

### INDEX TO COLOR TRANSPARENCIES

John Tagiuri, photographer, 2008

MA-163-8 (CT)	North elevation, same view as MA-163-1.
MA-163-9 (CT)	North elevation.
MA-163-10 (CT)	3/4 view from street looking southwest, same view as MA-163-2.

BEACON MARINE BASIN  
HAER MA-163  
INDEX TO PHOTOGRAPHS

MA-163-11 (CT)	Detail of street elevation, same view as MA-163-3.
----------------	--